

## UTAH 3600 COMPLIANCE INSPECTION REPORT

*Contract:* U-80887/84771

*Field Office:* UTC0300

*Operator(s):* Color Country Rock – Jeff Fawcett

*Project name:* Vermillion Sandstone Quarry- in Middle Kayenta Formation

*Location:* T41S R18W Sec 13 SENE

*Disturbance:* Operator has mined some material along both sides of the cuesta. GPS of site found 5.6 acres disturbed with approximately 0.5 acres in the interior of the site undisturbed.

*Hazardous Materials on Site:* None/The site is clean.

*Comments:* No recent activity- contract U 80887 for stacked rock expired on 8-30-09 and U-84771 for decorative rock expired on 7-11-07.

*Instructions to Operator:* Provide update on future plans/reclamation.

*Recommended Action(s):* Continue to monitor.

*Photographs Taken:* See Photographs below.



View of looking down the west side of the cuesta, showing the quarried sandstone bed within the Middle Kayenta Formation, weeds indicate no recent activity.

**RECEIVED**  
**DEC 01 2010**  
**DIV. OF OIL, GAS & MINING**





Overview looking down from the top of the access road.

Inspector: Russell Schreiner

*Date of Inspection:* November 23, 2010

Reviewed by: \_\_\_\_\_  
FM, St.George Field Office

Date: \_\_\_\_\_